Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-1036

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Fax:

Address: 1574 White AVE

Email Address:

Henderson, TN

Agency Contact: Murley, Rickey

Work Phone: Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-868-1093

Client Name:

Client ID:

Alt. Client ID: 16016SW-1036

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/15/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 7

Measures

ı	Measure 1 Seal	Ducts			Componen	ts			Inspected
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Mastic duct boots	Each	1					
2	Labor	Labor	Hour						
2	other Detail					****	,	,	
			1						
				Measur	e Sub Total:		,	Sub Total:	
	Field Notes:								

I	Measure 2 Infilti	ation Redctn			Componen	its		į	Inspected
C	omment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal pipes under kitchen sink,Storage closet off rec room repair wall and seal wall to ceiling	Each	1					
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal around vent pipe and plumbing box behind washer and dryer	Each	1					
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Seal wall to floor in both closets in blue room, Seal door to attic, Seal 2 attic access doors	Each	1					
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Seal pipes under all bath vanities	Each	1			1		
8	Labor	Labor	Hour						
(Other Detail						-,		
] []		
				Measur	e Sub Total:			Sub Total: [
	Field Notes:								

Measure 3 DW	H Pipe Insulation			Componen	ts		ı	nspecte
				Estimated		***************************************	Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
I Insulation	DHW Pipe Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail	7					1 [

			Measur	e Sub Total:			Sub Total:	
Measure 4 Atti	c Ins. R-19			Componen	ts A1		ı	nspecte
oommen.				Estimated			Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Insulation	Attic Insulation - Blown Cellulose -Add 6 inches	SqFt	560					
2 Labor		SqFt	560					
Labor	Labor	Oq! (L	
	Labor	Oq. 1				1		
	Labor	Oqri						
	Labor							
Other Detail	Labor			e Sub Total:			Gub Total:	

Report Run On: 5/15/2010

Measure 5 Atti	c Ins. R-19			Componen	ts A2		ı	nspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose -Add 6 inches	SqFt	560					
2 Labor	Labor	SqFt	560					
Other Detail								
			Measure	e Sub Total:] ;	Sub Total:	
Measure 6 Sto	rm Windows			Componen	ts 2W3,2 E3,2E		V2,2N1,	Inspected
	rm Windows			Componen Estimated	E3,2E		Actual	
Comment	Description / Comment	Units	Qty	•	E3,2E		,,	Inspected Total
Comment		<i>Units</i> SqFt		Estimated	E3,2E	2	Actual	
Comment # Material / Labor	Description / Comment		Qty	Estimated	E3,2E	2	Actual	
Comment # Material / Labor 1 Windows	Description / Comment Storm Window	SqFt	Qty 6	Estimated	E3,2E	2	Actual	
# Material / Labor 1 Windows 2 Labor	Description / Comment Storm Window	SqFt	Qty 6	Estimated	E3,2E	2	Actual	
# Material / Labor 1 Windows 2 Labor	Description / Comment Storm Window	SqFt Hour	Qty 6 150.1	Estimated	E3,2E	2 — Qty	Actual	

Client Name:

Client ID:

Alt. Client ID: 16016SW-1036

Work Order (Bid Form)

Work Order Name

Report Run On: 5/15/2010

DOE Weatherization Assistant Version 8.5.0

Page 5 of 7

Measure 7 DWH	Tank Insulation			Componen	ts		1	nspected
Comment								
				Estimated		*************************	Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipment	DHW Tank Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measure	e Sub Total:] ;	Sub Total:	
Field Notes:		***************************************	***************************************					
1								THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW
								1
Measure 8 CO N	lonitor is Needed			Componen	ts			nspected
Measure 8 CO N	lonitor is Needed		· · · · · · · · · · · · · · · · · · ·	Componen	ts			nspected
	lonitor is Needed		·	Componen Estimated			I Actual	nspected
	Monitor is Needed Description / Comment	Units	Qty			Qty		nspected
Comment		<i>Units</i> Each		Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items	Description / Comment		Qty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety	Description / Comment CO monitor	Each	Q ty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment CO monitor	Each	Q ty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment CO monitor	Each	Q ty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated			Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
Comment # Material / Labor 1 Health and Safety Items 2 Labor Other Detail	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

	Measure 9 Smo	ke Detector is Needed			Componen	ts		I	nspected
C	Comment				Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke detector	Each	1					
2	Labor	Labor	Hour	1					
	Other Detail]]	e Sub Total:			Sub Total:	
	Field Notes:								
			Work O	rder Gra	and Total:		Gran	nd Total:	and parameters